

Technical information

TI No.: 82.22U23249A
Distribution list: D
Distribution date: 10.07.2023
Valid until: 31.12.2025
The point of contact is the EvoBus after-sales service in each country

Model:	S 531 DT; S 516 HDH; S 511 HD; S 515 HD; S 516 HD/3; S 517 HD; Setra 510 LE; Setra 515 LE; Setra 518 LE; Tourismo; Tourismo M/2; Tourismo M/2 RL; Tourismo M/3; Tourismo L; Tourismo L RL; Intouro; Intouro M; Intouro L; Tourrider Premium; Citaro; Citaro G; Citaro K; Citaro LE MÜ; eCitaro
MODEL SERIES:	410010; 410130; 410131; 410201; 410210; 410211; 410241; 410251; 410390; 410391; 410394; 410540; 410550; 410555; 410560; 410570; 410575; 410710; 410730; 410750; 410850; 628035; 628036; 628056; 628255; 628405; 628526; 628630; 628631
TITLE:	Functional limitations of the 360° camera system (VC82)

COMPLAINT

When the automatically activated hazard warning lamps are switched on (e.g. by emergency brake assist), the Top View screen of the 360° system is not displayed. After deactivation by the driver, the 360° camera system suffers the following functional limitations:

- Triggering of Side View by the turn signals not working,
- Automatic monitor deactivation above 35 km/h not working,
- Vehicle activates only the 360° full screen display by default

CAUSE

Error in the function chart of the MUX/EAM control unit.

REMEDY

Program the MUX/EAM control unit with an optimised function chart.

MEASURE TYPE

The scope of the work is carried out as part of a Customer Service measure (KDM).

REPLACEMENT PARTS REQUIRED

Quantity	Designation	Number	Comment
1	Field solution	A 000 440 52 98	

OPERATION TEXTS

Operation no.	Operation text	Working time/h	Comment
12-1655	Program the MUX/EAM control unit	0.9	

The times apply for work at an hourly rate.

DEFECT NUMBER

Defect no.:	Designation
8297156	

CODEWORD

8222U23249

INTRODUCTION OF MODIFICATIONS INTO SERIES PRODUCTION

01.04.2023

WARRANTY AND GOODWILL SETTLEMENTS

Field measure type KDM (Customer Service measure): 100 % of costs will be accepted.

BUS/MCC	BUS/MCC-O
pp.	pp.
Markus Fischer	Barbara Hatziosifidou

Attachments

Ordering software for field solution and programming the MUX/EAM control unit

- : Instructions for requesting software

- Note concerning flashware ordering process.



Note

Data for flashware ordering process via Xentry-Flash:

TI No.: 82.22U23249A

Defect no.: 8297156

Codeword: 8222U23249