

**Subject: Engineering Information – Steering Wheel Button for Cruise Control and/or Radio Control are Not Responding When Pressed**

*This PI has been revised to end the need for gathering information from the field. Please discard PIE0752.*

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Cadillac	LYRIQ	2023	2023	—	—	—	—

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released May 25, 2023 Revised June 21, 2022 - Ended the need for gathering further information from the field.