



Preliminary Information

PIT6027 Cannot Program Accessory Keypad

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2023	All	All	All	All
GMC	Canyon	2023	All	All	All	All

Involved Region or Country:	North America
Condition:	Cannot program accessory keypad.
Cause:	Incompatible software.

At this time there is no software compatible with the accessory keypads but there may be a release at a future date. Do not attempt to install keypads at this time.

Version History

Version	1
Modified	06/01/2023 - Created on.



GENERAL MOTORS