

## GPOP - Issue Review System

**Part Number:** 68588637A\$, 68588639A\$, 68588643A\$, 68588647A\$, 68598819A\$,  
68611543A\$

**Part Description:** Occupant Restraint Controller

**Issue Description:** For concern of DTC B767-49 Left Impact Pressure Sensor-Internal Failure OR DTC B2768-49 Right Impact Pressure Sensor-Internal Failure, prior to replacement of any components please contact engineering at FCA Redacted Content for further assistance. If no response in 15 minutes, proceed with repair.