

## UPS CAMPAIGN N805 – LOW ENGINE OIL WARNING 23MY DEFENDER V8

UPDATE PRIOR TO SALE CAMPAIGN N805 – LOW ENGINE OIL WARNING	
AFFECTED MODELS	23MY Defender V8 ONLY
VOLUME AFFECTED	US 731 CAN 61
REPAIR	A concern has been identified on certain vehicles where a low engine oil warning message may incorrectly display on the Instrument Panel Cluster. A software update to the PCM is required.
REPAIR TIME	0.2 hrs + DIDO
CAMPAIGN LAUNCH	June 19th, 2023
Notes	Retailers should check the warranty portal to confirm affected VIN and following the bulletin service procedure must repair all affected vehicles prior to vehicle delivery. As of June 30 <sup>th</sup> , 2023, 189 US and 33 Canadian affected vehicles in new retailer inventory.