



Bulletin No.: PIT3010B
Published date: 07/12/2023

Preliminary Information

PIT3010B Service Stability System Message with DTC C0285 and/or C0286

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|----------|-----------------|--------------|------|-----|---------|----------------|
| | | | from | to | | |
| Cadillac | Escalade Models | 2002 | All | All | All | All |

Supersession Statement

This PI was superseded to update the condition section. Please disregard PIT3010A

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Service Stability System message on with DTC C0285 and/or C0286 caused by the Medium Pressure Accumulator Switch (MPA). A new MPA switch is now available from SPO parts.

Recommendations / Instructions

To correct this concern, order part number 88983914.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

