

Technical Service Bulletin

PSS 90 Audi Virtual cockpit speedometer needle flickers while driving

90 23 36 2071329/1 August 24, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, Q7, and Q8	2019	All	Virtual Cockpit

Condition

Customer states:

The red needle of the speedometer (Figure 1) flickers while driving.



Figure 1: Red needle of the speedometer flickers while vehicle is in motion.

Workshop Findings:

The condition can occur with the following circumstances:

- Flickering can be seen in standard view (large speedometer).
- Flickering can be seen in extended view (small speedometer).
- Flickering does not occur when stationary.
- The correct speed is displayed.
- The tachometer needle does not flicker.

Page 1 of 2

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin

Technical Background

Software issue in the virtual cockpit.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

- 1. Explain to the customer that a solution is expected to be available by the end of the 4th quarter of 2023 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
- 2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2071329) are subject to change and/or removal.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2023 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.