

---

<b>Reference</b>	SSM76053
<b>Models</b>	New Range Rover / L460 New Range Rover Sport / L461
<b>Title</b>	Front Overhead Console - Rattle
<b>Category</b>	Body
<b>Last modified</b>	14-Aug-2023 00:00:00
<b>Symptom</b>	107000 Interior Trim

---

**Content****Model / Model Year / Derivative:**

Range Rover / 22MY Onwards / All

Range Rover Sport / 23MY Onwards / All

**Situation:**

JLR Engineering are investigating customer reports of a 'rattle'/'creak' noise from the front overhead console/rear view mirror area.

**Action:**

Follow the instructions below.

**Service Instruction:**

- Select 'Fault and Breakdown'.
- Select 'Diagnose a fault'.
- Enter the following Symptom: Body > Trim and Ornamentation > Interior > Squeaks/Rattle/Clicks.
- Select the following test from the test plan 'Rattle From Overhead Console - Test'.
- Follow the on-screen instructions.

(Ref 000376788)

anBhdHRicnM7MjAyMy0wOS0wOFQxMzo1NjpxMC43ODdaOzEzNi4yMjYyUzQuMTEzOw==