

**Subject: Engineering Information - 3rd Row Release Strap has Fray Marks and/or Does Not Release to Fold Down Seat Back**

*This PI has been revised to end the need for gathering information from the field. Please discard PIE0745.*

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2020	2023	—	—	—	—
Chevrolet	Traverse						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released May 03, 2023 Revised August 08, 2023 - Ended the need for gathering further information from the field.