



Preliminary Information

PIT6054 Multifunction Inner Tailgate Disabling Procedure Inoperative

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2023 - 2024	All	All	All	All
GMC	Sierra	2023 - 2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	With QK2 - Multifunction Tailgate and without AVJ - passive entry
Condition	Multifunction Inner Tailgate Disabling Procedure Inoperative
Cause	If the vehicle is not equipped with RPO AVJ passive entry, it will not have the rear bumper antenna to allow the disabling of the inner tailgate.

Correction:

None, On vehicle without passive entry the inner tailgate cannot be disabled.

Version History

Version	1
Modified	08/28/2023 - Created on.



GENERAL MOTORS