



GROUP	MODEL
Product Improvement	2022-2024MY Carnival (KA4) Non-SX-Prestige
NUMBER	DATE
PI2301 (Rev 1, 09/10/2023)	August 2023

PRODUCT IMPROVEMENT CAMPAIGN

INSTALLATION OF STEEL REINFORCEMENT PLATES FOR 2ND ROW SEAT OUTER RAILS (PI2301)

SUBJECT:

This bulletin provides information to install steel reinforcement plates on the second-row seat outer rails in certain 2022-2024MY Carnival (KA4) LX/LXS/EX/SX vehicles (without relaxation/power seat feature) produced from January 4, 2021 through August 12, 2023. The campaign is to reinforce the mounting points of the 2nd-row seat to the floor and reinforce the seat rail at rail detachment, should a crash event occur. Follow the procedure outlined in this bulletin to install the two (2) outer rail reinforcement plates on the applicable vehicle. After completing the procedure, verify that the vehicle VIN is in the list of affected VINs.



PI2301
TEMPERARILY ON
HOLD PENDING
UPDATED PARTS

NOTICE

A Product Improvement Campaign is a proactive program of customer notification. There is no charge to the vehicle owner for repair.

Repair status for a vehicle can be viewed on Dealer+ (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on Web: Customer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is PI2301.