

GPOP - Issue Review System

Part Number: 6PQ601X7A\$, 6PQ611X7A\$, 6PQ621X7A\$, 6PQ631X7A\$,
6PQ661X7A\$, 6PQ671X7A\$, 6PQ681X7A\$, 6PQ701X7A\$,
6PQ721X7A\$, 6PQ731X7A\$, 6PQ761X7A\$, 6PY831X7A\$,
6PY841X7A\$, 6PY851X7A\$, 6PY861X7A\$, 6PY921X7A\$, 6PY931X7A\$,
6XZ181X7A\$, 6XZ191X7A\$, 6XZ211X7A\$, 6XZ221X7A\$, 7BQ361X7A\$,
7BQ371X7A\$, 7BQ381X7A\$, 7BQ391X7A\$, 7BQ401X7A\$,
7BQ411X7A\$, 7BQ421X7A\$, 7BQ431X7A\$, 7BQ441X7A\$,
7BQ451X7A\$

Part Description: CONSOLE Overhead

Issue Description: For concern of sunglass holder won't stay closed, WL OVERHEAD CONSOLE NOW OFFERS THE SUNGLASS BIN AS A SEPERATE SERVICEABLE PART.

The Sunglass Bin on the Overhead console as a separate Serviceable component~
COLOR PNs:
7TE35TX7A\$, 7TE35DX8A\$