

U116000 Bus keepawake stored

Topic number	LI54.10-P-076896
Version	1
Function group	54.10 - Battery, power supply, voltage converter
Date	9/8/23
Validity	Star 3 vehicles (206, 223, 232, 254, 294, 295, 296, 297)
Reason for change	

Complaint

12V message in IC when starting the vehicle.

Cause

SW updates need to be performed.

Remedy

Follow the guided test for FC U116000 in N73/3*1 EIS CU.

Perform the SW checks and updates.

Fully charge both 12V and 48V batteries.

After, perform a few drive/park cycles with at least 1 overnight park cycle.

If the 12V message is no longer present, release the vehicle.

Symptoms
Overall vehicle > Power supply > Battery/On-board electrical system > Battery/on-board electrical system indicator lamp > Battery charge indicator/consumer shutoff > Illuminates red
Overall vehicle > Power supply > Battery/On-board electrical system > Battery/on-board electrical system display message > Low voltage Charge battery

Control unit/fault code	
Control unit	Fault text
N73/3*1 - Electronic ignition lock - Central gateway (EZS) (GW223)	U116000 - A bus keepawake unit was detected. _

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note