

<b>Reference</b>	SSM76094
<b>Models</b>	New Range Rover / L460 (057311 → 020552)
<b>Title</b>	SV Signature Suite – Row 2 Deployable Table Not Stowing
<b>Category</b>	Body
<b>Last modified</b>	29-Sep-2023 00:00:00
<b>Symptom</b>	107000 Interior Trim

**Content****Model / Model Year / Derivative:**

Range Rover / 23MY / with SV Signature Suite (row 2 deployable table)

**Situation:**

JLR Engineering investigations have found reports of the row 2 table not stowing correctly on vehicles equipped with 'SV Signature Suite'.

When the SV Signature Suite is in the raised position a user may find they are unable to lower it by pressing the 'lower' button on the touch screen. The button will not be highlighted as it should be.

Note: Make sure the table leaves are closed and the table is pushed fully forward on its slides (the correct position for lowering). Refer to: iGuide -> Convenience Features -> Rear Centre Console Table - for operation instructions.

**Cause**

Faulty microswitch within the table assembly.

**Action**

Follow the instruction(s) below:

**SERVICE INSTRUCTION:**

Submit an Electronic Product Quality Report (EPQR). The EPQR must include the following information:

- A video attachment to show that the row 2 deployable table will not lower.

Send an email to: **SVHELP@JAGUARLANDROVER.COM** to request a microswitch repair kit.

Title the email: Request for microswitch repair kit / \*vehicle VIN number\*

Supply the following information in the email:

- VIN number
- EPQR number
- Retailer name
- Retailer full address for shipping repair kit
- Retailer contact name
- Retailer contact email address
- Retailer contact telephone number

**Do Not complete any further diagnostics or disassembly of the Signature Suite Console, this includes programming of modules.**

When the microswitch repair kit has been received, follow the instructions below.

1. Install a new microswitch for the SV Signature Suite row 2 table (see TOPIx Workshop Manual section: 501-12C - Instrument Panel and Console - [+] SV Signature Suite - Rear Floor Console Table Microswitch).
2. Test the SV Signature Suite functions to make sure they are now working as expected.

(Ref 000370478)