

GPOP - Issue Review System

Part Number: 68583952A\$

Part Description: Radio Frequency Hub Module RFHM

Issue Description: Prior to replacing RFHM module, please contact FCA Redacted Content Please verify wiring connections including proper connection with external Remote Start Antenna and that passive entry feature is also functional and that wiring to the LF antennas is correct. Verify key fob battery to be in the range above 2.4V to 3.1V.