

McLaren Artura - Alarm Microwave Sensors Relocation

SENSITIVITY: Restricted

Bulletin type:	Service Campaign
Reference number:	N/A
Campaign reference:	SCB 16 N 002
Attention:	Retailer Aftersales Managers, Retailer Service Managers, Retailer Service Advisors, Retailer Technicians, Retailer Parts Managers
Affected vehicles:	McLaren Artura
Situation:	Relocation of the alarm microwave sensors to reduce false alarm activations
Procedure:	Action affected vehicles during next Retailer visit. Please refer to the information outlined in this document to complete the required work
Date:	10 October 2023

This bulletin will cover:

-
1. Overview
 2. Parts Information
 3. Procedure
 4. Warranty Information
 5. Affected Vehicles
-

1. Overview

Through continuous product quality monitoring, it has been identified that false alarm activations can occur, in particular during wet weather, due to the sensitivity of the alarm microwave sensors within the vehicle's doors. To rectify this, McLaren Automotive has developed a solution whereby the alarm microwave sensors are relocated to a different position within both doors.



Image 1 New location of the alarm microwave sensor (1)

2. Parts Information

The below parts are required to action this rework and relocate the alarm microwave sensors. Parts are available to order as normal via Unidial 2.

Part Number	Part Description	Quantity Required
16MB610CP	FLY LEAD MICROWAVE SENSOR	2 (one per door)

All orders should be placed as usual on Unidial 2, for any parts queries please contact our Parts Customer Service Team:

EMEA – mclarencustomerservice@unipart.com

APACHI – mclarencustomerserviceap@unipart.com

AMERICAS – mclarencustomerservicena@unipart.com

To support timely completion of Campaigns, please plan your parts ordering in line with your impacted Vehicle Parc. Sufficient inventory in your facility to complete your vehicle Campaigns will build customer trust and promotes customer satisfaction. In turn, we are doing everything possible to best support you with the right stock in our central facilities so we can ship your orders quickly.

3. Procedure

To perform the required work, follow SIS instruction 'HA-RM-09M002-04-004 - Remove/Install Microwave sensor'. This contains the relevant work instructions and care points to ensure the required work is carried out to bring the vehicle up to current manufacturing standard.

4. Warranty Information

Submit a claim to the McLaren Warranty department following completion of the work, using the following details.

Description	Repair Time
McLaren Artura – Alarm Microwave Sensors Relocation	2.6 hrs (both doors)

5. Affected Vehicles

Affected vehicles will be flagged in the Retailer Portal when next opening a Workshop Visit related to the vehicle. Your Regional Aftersales Manager will also contact you with a VIN list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

The McLaren data classification policy applies to all full time, part-time and fixed term employees of McLaren and all workers including, contractors, consultants, suppliers, and third parties who have access to McLaren data and/or systems. This policy includes all information held by, or on behalf of, McLaren in any form and all information systems/services used by, or used to store data belonging to, McLaren.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited (“McLaren”) are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.