

# WPJ7 Workshop Campaign - Re-routing wiring harness in transmission

---

## WPJ7 Workshop Campaign - Re-routing wiring harness in transmission

ID Number	WPJ7
Models	911 GT3 / GT3 RS (992)
Model Years	2022 - 2023
VIN List	Attached
Number of affected VINs	13
Issue Description	<p>There is the possibility that the wiring harness in the transmission on the affected vehicles was not routed according to the specifications.</p> <p>If this is the case, damage to the wiring harness cannot be ruled out over the service life of the vehicle. As a result, a yellow warning message "Transmission faulty - reverse gear not available" would be displayed on the instrument cluster.</p> <p>For this reason, the routing of the wiring harness in the transmission must be checked and the wiring harness must be correctly laid, if necessary.</p>
What should Porsche Centers do?	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p><b>As of the time of this posting (10/13/23) the remedy is now available. Parts can be ordered via PPL as normal.</b></p>
TI Number	<a href="#">No. 105-23</a>
Customer Notification	To be sent at a later date.

### Required parts

Part number	Designation	Quantity/vehicle	Parts return*
-------------	-------------	------------------	---------------

---

## WPJ7 Workshop Campaign - Re-routing wiring harness in transmission

PAF009388	Countersunk screw with internal serration, M6 x 25	13 pieces	No
9P1321359	Oil pan	1 piece	No
PAF008528	Screw plug with sealing ring M18 x 1.5	1 piece	No
00004330513	Transmission oil for double-clutch transmission oil PENTOSIN FFL 3 1.0 liter.	approx. 5 liters	No
PAF910423	All-round screw lens head screw M6 x16	5 pieces	No

\*The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the remanufactured parts process or be scrapped.

## Warranty processing

### Validity:

This current Workshop campaign will be carried out by August 2nd, 2028 and will be closed on that date. Please note that warranty claims can only be processed up to this date.

### Scope 1:

Damage number	WPJ7 66 000
Repair Code	1
Labor time	267 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

## Customer mobility

If requested, mobility for the affected customer can be ensured by offering a suitable replacement vehicle. Please invoice this additional service via WWS with the campaign scope.

---

## Attachments

- [1. VIN\\_List\\_Report\\_WPJ7\\_2023-10-13\\_V2.xlsx](#)