



SIB 31 01 23
SERVICE SOLUTION: Apparent Leak Front Fork Cap

MODEL

| Model | Type Code | Model Description |
|-------|-----------|-------------------|
| KM3 | 0E83 | M 1000 R |
| K67 | 0E63 | S 1000 R |

SITUATION

On the above listed vehicles, lubricant residue can be found on the fork cap on the right side telescoping fork. Vehicles with caps 31 42 1 754 557 and 31 42 1 757 701 can show this residue.



These are not leaks at the cap, but assembly grease residue.

Forks with this apparent leak have been received and leak testing was performed. **NO** leaks could be detected.

PROCEDURE

In the event of an apparent leak complaint, clean the cap area with a suitable cleaning solution.

QUESTIONS REGARDING THIS BULLETIN

| | |
|---------------------|---|
| Technical inquiries | Contact the BMW Technical Support Group via TSARA |
| Warranty inquiries | Submit an IDS ticket to the Warranty Department |
| Parts inquiries | Submit an IDS ticket to the Motorrad Parts Department |

Supporting Materials

[picture_as_pdf 31 01 23 SERVICE SOLUTION - Apparent Leak Front Fork Cap.pdf](#)

