



Bulletin No.: PIT6064A  
Published date: 10/4/2023

# Preliminary Information

## PIT6064A Unable to Configure Power Take Off (PTO)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500HD/3500HD	2024	All	All	L5P	MGU
GMC	Sierra 2500HD/3500HD	2024	All	All	L5P	MGU

Involved Region or Country	North America
Additional Options (RPO)	PTO - Power Take Off
Condition	A technician may find that they are unable to transfer settings to the Power Take Off Module when trying to configure the PTO system. When using GDS 2 to configure the PTO system, the settings appear to have taken, but PTO will not operate.
Cause	The cause of the condition may be a software anomaly.

Correction:

Engineering is aware of this condition and is working on an updated software to remedy this concern.

Version History

Version	<b>1</b>
Modified	09/27/2023 - Created on. 10/04/2023 - Updated to change correction information.



GENERAL MOTORS