



Bulletin No.: PIT6075  
Published date: 10/17/2023

## Preliminary Information

### PIT6075 Service Brake System Message , Code C2A17 Stored

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2023	All	All	All	All
GMC	Canyon	2023	All	All	All	All

<b>Involved Region or Country:</b>	North America
<b>Condition:</b>	Service Brake System message, code C2A17 stored in BSCM.
<b>Cause:</b>	Software anomaly.

#### Correction:

Charge and test the battery , perform SPS reprogram on the BSCM using procedures in eSI .

#### Version History

<b>Version</b>	1
<b>Modified</b>	10/17/2023 - Created on.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.