

## GPOP - Issue Review System

**Part Number:** 68156064A\$, 68156065A\$, 68156066A\$, 68401933A\$, 68469535A\$,  
68575999A\$, 68576205A\$, 68576206A\$

**Part Description:** SWITCH Headlamp

---

**Issue Description:** Before replacing the Headlamp Switch, due to an issue on the I/P Dimmer. Please follow the next steps to corroborate if the Headlamp Switch is malfunctioning:

- 1.- Please disconnect and reconnect the headlamp Switch. And verify if the issue is corrected.
- 2.- Review the resistance value between Pins 6 & 3. The value should be around 5.74 KOhms, when in the lowest position to 311 ohms in the top position (Parade Detent).

If a problem is found in the resistor values. Please replace the Switch.