

STAR ONLINE PUBLICATION
















Case Number: S2309000009

Release Date: October 2023

Symptom/Vehicle Issue: GG/GC Oil Change Monitor Reset

Repair Procedure: After a complete engine oil change to reset the Oil Change Monitor, connect the scan tool to the vehicle then perform the following:

1. Go to the IPC, then go to "Miscellaneous Functions" menu and run the "Reset Service Information" routine.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.

Stellantis US LLC Version 4.5 07/21/2022



STAR ONLINE PUBLICATION
















2. Go to the PCM, then go to "Miscellaneous Functions" menu and run the "Reset oil change indicator" procedure.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.

Stellantis US LLC Version 4.5 07/21/2022