



Technical Service Bulletin

90 Lane change assist radars cannot be calibrated after replacement

90 23 67 2072568/1 December 22, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A5 Cabriolet, and S5 Cabriolet	2012 – 2017	All	Lane Change Assist
A5, and S5	2012 – 2016		
Q5, and SQ5	2013 – 2017		
A4, A4 allroad, S4, and Q5 Hybrid	2013 – 2016		
RS 5, and RS 5 Cabriolet	2013 – 2015		
A8, and S8	2014 – 2017		
A6, S6, A7, S7, RS 7, and Q3	2015 – 2018		
A3, A3 Cabriolet, S3, and S3 Cabriolet	2015 – 2016		
TT, TTS, and TT Roadster	2016 – 2018		
A3 e tron quattro	2016		
TT RS	2018		

Condition

Workshop findings:

- After one of the two lane change assist control units (J769 or J770) (address word 003C) has been replaced, it cannot be used and/or calibrated.

The following DTC or DTCs and symptom code(s) may be stored in the lane change assist control module -J769-/-J770-, (address word 003C):

- **DTC B201200:** Data set implausible.

Technical Background

Shortcomings in the ODIS test plan.



Technical Service Bulletin

Production Solution

Not applicable.

Service

Perform the **Guided Function** “3C – Replace control module J770” for diagnostic address **3C**, regardless of which control unit (J769 or J770) was replaced. This ensures that the parameters will be set correctly for both control units (J769 and J770). It is essential that you calibrate the lane change assist afterwards.

NOTICE

After replacing a control unit, it may be necessary to finish the current diagnostic session and re-start diagnosis. Doing so re-initializes the control units that have been replaced and allows the correct version of the lane change assist (1.0, 1.5 or 2.0) to be identified by the test plan for the purposes of calibration.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2072568**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.