

9004542

09/15/2023

MY12-13 PF MY14-19, 21 KL MY19, 21, 23  
DD MY22 D2 MY20 RU MY21, 23 WL  
MY21 M4, M6 MY23 H6

## GPOP - Issue Review System

**Part Number:** 56046503A\$, 68298334A\$, 68298468A\$, 68384225A\$, 68384226A\$,  
68483780A\$, 68507366A\$, 68576492A\$, 68607452A\$

**Part Description:** Rain Sensor

---

**Issue Description:** Before replacing the rain sensor during a front windshield replacement inspect the part for part numbers. If you have part numbers; 68507366, 68483780, 68384226 or 68384225, these parts do not utilize a replaceable gel pad, only replace the sensor for a missing or damaged gel pad. For part numbers 68298334, 68298468, 68607452 or 68194700 the gel pad should be replaced during all windshield replacements and can be ordered through MOPAR, complete sensor replacement is not necessary. Contact: FCA Redacted Content for further questions If no response in 15 minutes, proceed with repair.