GPOP - Issue Review System

Part Number: 05038788A\$

Part Description: LIFTER, Hydraulic Roller Deactivating

Issue Please do not replace MDS lifters because the disconnecting pin is not lined up, this is **Description**: normal and not a defect.