

GPOP - Issue Review System

Part Number: 68263397A\$

Part Description: Blindspot Module

Issue For concern on Blindspot Module setting U11FB-00 Lost Communication with Left
Description: Blind Spot Sensor, U11FA-00 Lost Communication with Right Blind Spot Sensor.
Some vehicle(s) where the Blindspot Module was replaced had no issues found with the Blindspot Module after testing. Please verify no wiring or connector issues are present prior to module replacement. Prior to replacing the Blindspot Module, Please Contact Engineering:
FCA REDACTED CONTENT If no response in 15 minutes, please proceed with repair.