



STAR ONLINE PUBLICATION



Case Number: S2308000141

Release Date: November 2023

Symptom/Vehicle Issue: Park Brake Warning Lamp Illuminated and Flashing, Cluster Warning Message to “Service Park Brake”

Customer Complaint/Technician Observation: The owner complains the park brake warning lamp is on and is flashing. The Instrument Panel Cluster (IPC) may display a “Service Park Brake” Message on some vehicles. The technician observed the Diagnostic Trouble Codes (DTCs)

C060B-00 or C0610-00 Left or Right Park Brake Actuator Control Circuit/Open
C060D-00 or C0612-00 Left or Right Park Brake Actuator Control Circuit High
C10EA-00 Left Park Brake Actuator.

Repair Procedure: Verify all connections are secure using the push-pull-push method looking for any Terminal Pushouts or Spread terminals at the component actuator, inline connectors Xy890A, Xy891A, Xy810A or the Module Brake System Control as needed Fig 1, 2, 3.




Fig 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.


Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.



STAR ONLINE PUBLICATION



Left or Right rear actuators



XY810A






Fig 2

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.



STAR ONLINE PUBLICATION



NOTE: This Harness Assembly is a COMPOSITE depicting all available options. Some connectors may not be present on vehicle.

Fig 3

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.