



Bulletin No.: PIT5947B  
Published date: 12/7/2023

# Preliminary Information

## PIT5947B No Selection To Reset The Fuel Filter Life In The DIC

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2022 - 2023	All	All	3.0L LM2	All

Involved Region or Country	North America
Condition	Some customers may comment that they are unable to reset the fuel filter monitor system. When scrolling through the DIC there is no selection for fuel filter life reset.
Cause	The cause of this condition is a radio calibration.

**Correction:**

To correct this concern, reprogram the radio by following SI procedure for "A11 Radio: Programming and Setup".

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810335	Radio Reprogramming with SPS	Use Published Time

Version History

Version	3
Modified	09/26/2022 - Created on. 02/07/2023 - Update to the Cause, Condition and Warranty sections. 12/07/2023 - Update to the model list

