



Preliminary Information

PIT6116 Hands Free Liftgate Logo Inoperative

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2020 - 2024	All	All	3.6L (LFY)	All
Cadillac	XT5	2020 - 2024	All	All	3.6L (LFY)	All
Cadillac	XT6	2020 - 2024	All	All	3.6L (LFY)	All
Chevrolet	Blazer	2020 - 2024	All	All	3.6L (LFY)	All
Chevrolet	Traverse	2020 - 2024	All	All	3.6L (LFY)	All
GMC	Acadia	2020 - 2024	All	All	3.6L (LFY)	All

Involved Region or Country	North America
Condition	The hands free liftgate logo may be inoperative. The hands free liftgate will work. You will also be able to command the lamp on. The lamp may work with one fob and be inoperative with the other.
Cause	The Keyless Entry Module may be disabling the lamp.

Correction:

Inspect in the Keyless Entry Module in Data Display for the Approach Detection Disable Reason. Go into the Keyless Entry Module under Configuration/Reset Function and perform the Clear Approach Detection Disable Reason.
If the condition still exists to follow SI diagnostics.

Version History

Version	1
Modified	01/24/2024 - Created on.



GENERAL MOTORS