

**On-car analysis list from February 13th, 2024**  
**please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
<b>Powertrain</b>	Atlas, Cross Sport	23-24	All	All	Exhaust/Heat shield noise	Customer states rattle from below the vehicle <b>(Untouched vehicle)</b>
	Atlas, Cross Sport, Taos, Jetta	24	All	All	MIL-on P0442	Customer states Mill-on, P0442 stored in ECM memory <b>(leak must be from fuel cap area)</b> <b>(Untouched vehicles)</b>
	Taos	23-24	All	All	MIL-on P0462 and/or P0463	Customer states Mill-on, P0462 and/or P0463 stored in ECM memory <b>(Untouched vehicles)</b>
	All	23-24	All	All	Fuel Gauge	Customer states fuel gauge does not read full after filling the fuel tank <b>(Untouched vehicles)</b>
	Tiguan	22-23	All	All	MIL-on P0442	Customer states MIL-on, P0442 stored in ECM memory <b>(Untouched vehicles)</b>
<b>Electric</b>	Tiguan, Atlas, Cross Sport	22-24	All	All	Seat Fault B201000, B135354 and/or B135454	Customer states seat memory is inoperative <b>(Must have B201000, B135354 and/or B135454 in address 36)</b> <b>(Untouched vehicle)</b>
	Atlas, Cross Sport, Jetta, Taos, Tiguan	22-23	All	All	Key Battery	Customer states key FOB lock/unlock functions do not work via button press (not KESSY). <b>(Must have B147918 and/or B147A18 in Address 09)</b>
	ID.4	23	All	All	Seat Fault B135554	Customer states seat memory is inoperative <b>(Must have B135554 in address 36)</b> <b>(Untouched vehicle)</b>
	ID.4	23-24	All	All	Sunroof	Customer states sunroof cracked <b>(Untouched vehicle)</b>
	ID.4	23-24	All	All	Rear Spoiler	Customer states rear spoiler is loose <b>(Untouched vehicle)</b>
	Tiguan	24	All	All	Seat Cover	Customer states driver and/or passenger front seat cover discolored <b>(Untouched vehicle)</b>
	Tiguan	22-23	All	All	Seat Belt	Customer states seat belt won't retract