



SSM 52264 2020-2024 Aviator - Loadspace Trim Panel Vent Register Now Serviced Separately

Some 2020-2024 Aviator vehicles may exhibit concerns that require loadspace trim panel vent register replacement. The vent register is now available separately (service base part number 19893). It is no longer necessary to replace the entire loadspace trim panel.