



**Dealer
Service
Bulletin**

NO.: 7SB002-24-02A

SECTION: Body

DATE: February 27, 2024

MODELS


AFFECTED: View, Navion, Adventurer, Vista, Sunstar

SUBJECT: Rear Cap Installation

PLEASE FORWARD THIS INFORMATION TO YOUR RV SERVICE, WARRANTY & PARTS MANAGERS.

This bulletin is to advise you of a change to the rear cap installation process. We have eliminated the need for self-leveling sealant on the front edge of the rear cap in favor of a clip-on rubber seal. This will eliminate complaints of sealant voids and cracks in this area.

Please be sure to pass this along to your staff so they are aware that the area is not missing sealant. Reference photos below.



Thank you for your continued support of Winnebago.

Dean Casad
Director of Customer Support

IMPORTANT THAT ALL PARTS AND SERVICE PERSONNEL READ AND INITIAL

| PARTS MANAGER | | SERVICE MANAGER | | SERVICE PERSONNEL | | | | PARTS PERSONNEL | | | | PAGE | |
|---------------|--|-----------------|--|-------------------|--|--|--|-----------------|--|--|--|--------|--|
| | | | | | | | | | | | | 1 OF 1 | |