

QUARANTINE N871 – RIGHT HAND LOWER A PILLAR BOLT

UPS QUARANTINE N871 – RIGHT HAND LOWER A PILLAR BOLT	
AFFECTED MODELS	24MY Discovery Sport
VOLUME AFFECTED	Retailer Inventory US 39 CAN 2
REPAIR	On 2024 model year 7 Seat Discovery Sport vehicles, some body shells have been made where the righthand side lower A-Pillar bolt may not have been fastened to the specified torque. This quarantine has been raised to hold vehicles pending further investigation and the development of a repair procedure.
REPAIR TIME	TBC
CAMPAIGN LAUNCH	TBC
NOTES	BBSS shows 41 affected units in retailer inventory. Additional vehicles are being held in ports of entry.