

WRB6 Stop Delivery - Replacing Gateway control unit

WRB6 Stop Delivery - Replacing Gateway control unit

Important information

PORSCHE CENTERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY.

ID Number	WRB6
Models	911 (992) Taycan (Y1A / Y1B / Y1C) Panamera (971) Cayenne (9YA / 9YB)
Model Years	2022 - 2024
Number of Affected VINs	1,665
VIN List	Attached
Issue Description	<p>A gateway control unit was installed on the affected vehicles which does not meet the required market-specific requirements.</p> <p>For this reason, the gateway control unit must be replaced before vehicle delivery to customer.</p>
What should Porsche Centers do?	<p>Please do not deliver the subject vehicles until the repair is completed.</p> <p>The vehicles may be driven only for loading and unloading purposes in the transport chain prior to remedy. Test drives are to be omitted.</p> <p>The repair is available as of 2/23/24 for vehicles with an allocated part.</p>
Parts Ordering Instructions	<p>Gateway parts are being allocated and are not available for order at the current time. Please refrain from ordering Gateways and inquiries about the availability of Gateways. All other supporting hardware can be ordered via PPL as normal.</p>
TI Number	No. 22-24

Attachments

1. [VIN_List_Report_WRB6_2024-02-23_V2.xlsx](#)