

Technical Service Bulletin

40 Noises from the front end and dash panel, noise is heard when the vehicle is moving 40 24 75 2047920/9 March 8, 2024. Supersedes Technical Service Bulletin Group 40 number 23-68 dated September 7, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All Audi Vehicles	2020 – 2025	All	Not Applicable

Condition

REVISION HISTORY				
Revision	Date	Purpose		
9	-	Revised Warranty (Updated Labor Operations)		
8	09/07/2023	Revised Service (Updated Tip)		
7	08/08/2023	Revised header (Added model years)		
		Revised Warranty (Updated Labor Operations)		

Customer states:

- There is a buzzing, booming, humming, whistling, or a similar noise from the front end.
- The noises can possibly be heard from the steering area or behind the dash panel.
- · The noises may also be perceived as tire rolling noises.

Workshop findings:

The noises can be reproduced in a test drive.

Technical Background

Mechanical damage on the wheel bearing of the front axle.

Production Solution

Not applicable.

Service

The noises from the wheel bearing can be transmitted via the steering into the vehicle interior.

Because of the proximity, it can be difficult to distinguish wheel bearing noises from rolling noises.



Technical Service Bulletin

Therefore, with such noises, check whether the wheel bearings of the front axle may be the source and replace the affected component. The following steps are helpful:

- 1. Does the frequency issue rise as the speed increases or does the sound get higher?
- 2. Does the noise get louder when steering?
- 3. Is the noise still present when slowing down?
- 4. Is the noise amplified on the steering wheel/airbag well?
- 5. Can the vibrations be felt on the unpressed coil spring when the wheel is turning?



Tip: Please precisely locate the source of the noise with acoustic testers and/or PICO tool. It is possible that a noise perceived on the left side of vehicle is caused by the right wheel bearing. The front wheel bearings should not be replaced in pairs.

If the cause of the noise cannot be traced to a wheel bearing, continue the analysis on other components.

Warranty

Claim Tuna.						
Claim Type:	• 110 up to 48 Months/50,000 Miles.					
	G10 for CPO Covered Vehicles – Verify Owner.					
	 If vehicle is outside any warranty, this Technical Service Bulletin is inforonly. 					
Service Number:	4057					
Damage Code:	0020					
Labor Operation:	Replace wheel bearing	4057 5550				
	A4, A5 (minus Cabriolet), A6, A7, A8, e-tron GT, Q5, Q7, Q8, and R8		See SRT with			
	Replace wheel bearing	4050 5550	associated operations			
	A3, A5 Cabriolet, e-tron, Q3, Q4 e-tron, e-tron quattro, Q8 e-tron, and TT					
Diagnostic Time:	GFF	No allowance	0 TU			
	Road test prior to service procedure	0121 0002	10 TU			
	Road test after service procedure	0121 0004	10 TU			
Claim Comment:	As per TSB 2047920/9					

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.				
Part Number	Part Description	Quantity		
See ETKA	Wheel bearings	1		
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA		

Additional Information

All parts and service references provided in this TSB (2047920) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.