



Technical Bulletin
01.2024

Contents

Item	Subject	Model Affected
.1	Triumph Diagnostic Tool - Autoscan Support	Speed 400, Scrambler 400 X

Item: .1
Description: Triumph Diagnostic Tool - Autoscan Support
Model Affected: Speed 400, Scrambler 400 X

We would like to advise dealers that the Triumph Diagnostic Tool Autoscan feature does not currently support the above models.

The ECM Status feature is currently available for the above models and includes checks for latest calibrations and stored DTCs.

Dealers are requested to perform an ECM Status Report on the above models at PDI and at every service or visit to the dealership. Dealers must ensure that all motorcycle calibrations are up to date and that there are no DTCs stored before customer handover.