



# Service Bulletin

Bulletin No.: 24-NA-049

Date: March, 2024

## INFORMATION

**Subject:** Information on Blazer EV Police Vehicle Air Deflector Installation


Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Blazer EV	2024	2024	-	-	All	All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	On Blazer EV POLICE vehicles during PDI the dealer may find that the front air deflectors are too long and interfere with an underbody shield.
<b>Cause</b>	The cause of the condition may be due to the aero panel was added after the air deflectors were developed.
<b>Correction</b>	Trim the air deflectors like illustrated below.

### Service Procedure

**Important:** Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

If you encounter a vehicle with the above concern, trim the air deflectors in the locations illustrated below.



6576072



6576071

### Parts Information

No parts are required for this repair.

Version	1
Modified	Released March 15, 2024

