

**Suzuki Motor Corporation**

4520 Shirasuka, Kosai City,
Shizuoka 431-0451 JAPAN

April 10th, 2024

EPN-2693

To: Suzuki Overseas Distributors

Atten: Presidents, Sales/Marketing Managers, Parts/Accessories Managers

SUBJECT: Sales Suspension of Accessory Bar for DL1050

Dear Sirs and Mesdames,

We regret to inform you that we are suspending the supply of Accessory Bar (p/n 990D0-06L00-030) for DL1050 from Magyar Suzuki again even though we announced the sales resumption in EPN-2688 which issued on March 29th, 2024.

The reason for the suspension was that the bolts might interfere in the weld bead of accessory bar. MSC have returned all the stock and received inspected products from the supplier. However, we found some stock of defective ones again during stock check. Due to this reason, we suspend the delivery until quality check completion at MSC.

In EPN-2645, we requested to suspend selling both of your warehouse and dealer stock. If you find defective stock, please send parts claims to MSC.

We apologize for your inconvenience caused on this matter. Your kind understanding and patience would be highly appreciated.

Yours faithfully,

A handwritten signature in blue ink that reads 'Y. Takahashi'.

Yoshiyuki Takahashi

Group Manager

Accessory Group

Spare Parts and Accessories Administration Department

Kosai Office

Suzuki Motor Corporation