



Preliminary Information

PIT6135 Camera App Missing From Radio Display

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2024	All	All	All	All
GMC	Canyon	2024	All	All	All	All

Involved Region or Country	North America, Middle East, Israel, South Korea
Additional Options (RPO)	UVB
Condition	Some customers may comment that the camera application is missing from the radio display.
Cause	The cause is a software anomaly.

Correction:

General Motors is aware of this issue and is working on a solution.

Please do not replace the radio, display or camera for this concern.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3486058	Verify camera app is missing from radio display	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	03/19/2024 - Created On.



GENERAL MOTORS