



Volvo Battery Electric Vehicle (BEV) - Air Conditioning Blowing Warm Or Not Blowing Cold Enough



✓ Internal Content

PIL-202885

Published 30 April 2024

Valid for

Volvo - VNRe Model years 2022 to current

Solution

- Phase 1 trucks may experience a complete lack of cold air blowing from the A/C system when one or both compressors fail to activate.
- Phase 2 trucks might still produce cooled air, but it may not reach the desired level of coldness due to compressor activation issues.

When diagnosing a customer report of warm air from the vents or the air conditioning not being cold enough:

1. Check to ensure that the A/C compressor(s) are engaging when the air conditioning is turned on and the temperature selection is set to cold.
2. **If one or both A/C compressors fail to engage:** Verify parameter P1KQI is set to 1.



Tags

volvo

ac

bev

cold air

warm air

Make and Model > Volvo > VNR Electric

Vehicle System > HVAC

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article