



## **SSM 52517 2024 F-150 - Non-Lightning - Air Conditioning (A/C) Inoperative, Lack Of Air Flow, And/Or Evidence Of Evaporator Freezing**

Some 2024 F-150 vehicles equipped with a gasoline, hybrid or flex fuel engine (non-Lightning) may exhibit inoperative A/C, lack of air flow and/or evidence of the evaporator freezing. This may be due to the software level of the heating, ventilation and air conditioning (HVAC) module. Reprogram the HVAC module using the latest software level of the FDRS diagnostic scan tool. Follow all on-screen instructions carefully to complete all coordinated module software updates. For claiming, use causal part RECAL and use applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.