

TRANSFER CASE NOISE

Customer Voice:

- Noise while driving or fluid leaking from middle of vehicle.

Technical Description:

- The output flange on the transfer case is possibly not seated correctly.

Status:

- Inspect the transfer case for any areas of fluid leak.
- Refer to the TOPIx workshop manual for repair instructions.

Refer to TOPIx 315-00C: Transfer Case - INGENIUM I6 3.0L Petrol,
or 315-00D: Transfer Case - V8 T/C 4.4L Petrol

Range Rover

- 24MY Range Rover Sport

