

HVAC SYSTEM VENT CONTROLS

Customer Voice:

- A customer may report lack of airflow from the face vents and or a whistle type noise from the defroster vent area.

Technical Description:

- This may be caused by the HVAC face vents being closed when the face mode operation is selected.

Status:

- New for Range Rover L460 mode variants, instead of having thumb wheels on the face vent registers to open and close the individual vents, the individual vents are controlled electronically through the touch screen.
- Depending on the mode and temperature selected, the face registers may close automatically, then when the face vent mode is selected the registers may not automatically open.
- Should a customer express a concern, please verify that the individual face vent registers are open on the touch screen menu.
- The HVAC modes and register controls are covered in the OHB.

Range Rover

- 23-24MY Range Rover





Ensure that the particulate matter sensor is connected under the instrument panel.

