

Technical Service Bulletin (TSB)
Air Trapped in Steering Damper Warranty Extension XF1

REFERENCE:	TSB: 23-041-24 GROUP: 23 - Body	Date:	May 30, 2024	REVISION:	23-079-23
VEHICLES AFFECTED:	2018 - 2020 (JL) Jeep Wrangler 2020 (JT) Jeep Gladiator This bulletin applies to vehicles built on and before August 11, 2020 (MDH 0811XX).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH	
CUSTOMER SYMPTOM:	A shimmy in the steering wheel after hitting an irregularity on the road surface (symptom is more prevalent in cold temperatures).				
CAUSE:	Air trapped in the steering damper				

This bulletin supersedes Technical Service Bulletin (TSB) 23-079-23, date of issue June 28, 2023, which should be removed from your files. All revisions are highlighted with **asterisks**** and include an updated LOP time.**

REPAIR SUMMARY:

This bulletin involves replacing the steering damper.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
02-15-20-95	Damper, Steering – Replace (1 - Semi-Skilled)	4 - Chassis	**0.4 Hrs.**
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	CCUKV411AD	Damper, Steering	JL Vehicles
1 (AR)	CXALXF12AA	Damper, Steering	JT Vehicles

DIAGNOSIS:

If the customer describes any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Replace the steering damper. Refer to the detailed service procedures listed in DealerConnect>Service Library under: 19 - Steering / Linkage / Damper, Steering / Removal and Installation.

POLICY:

Vehicles included in this Technical Service Bulletin have a Warranty Extension to an 8 Year warranty extension or 144,840 km (90,000 mi) from in service date warranty period for this repair. See Warranty Bulletins: U.S. D-23-09 and Puerto Rico ID-23-10, for details associated with the Warranty Extension.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.