



## STAR ONLINE PUBLICATION



**Case Number:** S2408000058

**Release Date:** June 2024

**Symptom/Vehicle Issue:** B22A9-49-ECU Internal Performance-Internal Electronic Failure Sets in the Security Gateway Module (SGW) Erroneously

**Technician Observation:** When connecting a scan tool to the vehicle, the technician may observe Diagnostic Trouble Code (DTC) B22A9-49 as stored in the SGW.

**Discussion:** The above stored code has no owner functional impact. Clear the DTC with the scan tool and review and update the SGW with the most current level of software available. No parts replacement required. Follow normal DTC diagnostics if the fault is active.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

**Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.**