

Diagnostic Sheet

FROM: Maserati TSO

TO: Maserati Network



PERSONAL SERVICE LAB

MASTERS OF CARE

Grecale –Axle shaft Clicking Noise - Tech Tip

DATE: June 6, 2024

This Diagnostic Sheet serves as a guide and provides additional diagnostic info for possible Axle shaft noise.

MODELS: M182 Grecale (All MY).

CONCERN: Front/rear clicking noise while maneuvering the vehicle

1. Remove the M24 axle nut (Pic.1) and thoroughly clean the grooves and hub thread with brake cleaner (Pic. 2).
2. Apply Molykote copper paste as illustrated – (Pic.3)
3. Replace the axle nut (component #12 in spare parts table 03.22-2 FRONT WHEELS TRANSMISSION)
4. Perform axle shaft nut tightening procedure as indicated in the workshop manual



Picture 1



Picture 2



Picture 3

In case of repeated concern, open a BOL as "Support Request" and provide video of the noise and detail of any additional activity done.

Please do not hesitate to contact us for any questions you may have.

Kind regards,

TECHNICAL SERVICE OPERATIONS