



Analysis Worksheet	
Topic	Q4 Roof panel buttons inop
Model(s) affected	2022-2024 Q4
Documentation needed	<p>Before performing work on the vehicle, proceed as follows:</p> <ol style="list-style-type: none"> 1. Check all functions of the roof module, which functions do not work? 2. Are functions restored after a key/sleep cycle? 3. Are functions restored if fuse power is temporarily removed? 4. Disconnect/reconnect module. Are functions restored? 5. Are you able to restore functionality in any other way? If so, describe.
Questions	<ul style="list-style-type: none"> • Do the functions work intermittently or always inoperative? • Does temperature have an affect? • Do functions start/stop working during a drive cycle? • Are there any warnings?
Other information: <small>(Please include any other useful information from the customer or found during diagnosis.)</small>	
Note:	<ul style="list-style-type: none"> • Information requested in these worksheets update frequently. Please always use the latest worksheet on Elsa2Go. • Please include all information requested in the worksheet up front when submitting the WEB ticket to TAC.