

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager

Freightliner Dealers – U.S. and Canada
 Western Star and Sterling Dealers – U.S. and Canada
 FCCC Dealers – U.S. and Canada
 Thomas Built Buses Dealers – U.S. and Canada
 Direct Warranty Customers – U.S. and Canada
 Detroit Diesel Distributors
 Export Distributors

Daimler Truck North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090

800-547-0712

Portland, Oregon 97208-4090

If you have questions about this Letter, please submit your inquiry using the **WSC App on the DTNA Portal**

REF #: ICI24-024

Effective: 06/13/24

Release: 06/13/24

SUBJECT: SF698 – Revised Bulletin

This letter is to inform you that a revised bulletin for Recall SF698 – Western Star Heated Headlight Parameters is available on DTNA Portal. Please print and use the revised bulletin for all work under SF698 from this point forward.

REVISION: Clarifying statements and a figure were added to the work instructions between steps 8 and 9 regarding “grayed out” XMC parameters.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the Warranty Support Center (WSC) located on the DTNA Portal.

RÉF # : ICI24-024

Effectif : 06/13/24

Publication : 06/13/24

OBJET : SF698 – Bulletin révisé

La présente lettre vise à vous informer qu'un bulletin révisé pour le rappel SF698 – Paramètres des phares chauffants Western Star est disponible sur le portail DTNA. Veuillez imprimer et utiliser le bulletin révisé pour tous les travaux effectués dans le cadre de la SF698 à partir de maintenant.

RÉVISION: Des énoncés de clarification et un chiffre ont été ajoutés aux instructions de travail entre les étapes 8 et 9 concernant les paramètres XMC « grisés ».

Si vous avez des questions ou avez besoin de plus amples informations, communiquez avec le service des campagnes de garantie en envoyant une demande par l'intermédiaire du Centre de soutien de la garantie (WSC) situé sur le portail DTNA.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.