

On-car analysis list from June 10th, 2024
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Atlas, Cross Sport	23-24	All	All	Exhaust/Heat shield noise	Customer states rattle from below the vehicle (Untouched vehicle)
	Atlas, Cross Sport	24	All	All	MIL-on P0442	Customer states Mill-on, P0442 stored in ECM memory (leak must be from fuel cap area) (Untouched vehicles)
Electric	Atlas, Cross Sport, Jetta, Taos, Tiguan	22-23	All	All	Key Battery	Customer states key FOB lock/unlock functions do not work via button press (not KESSY). (Must have B147918 and/or B147A18 in Address 09)
	Tiguan	22-23	All	All	Seat Belt	Customer states seat belt won't retract
Body	Atlas, Cross Sport	24	All	All	Door Fit	Customer states door fitment between panels not correct (Untouched vehicles)
	Atlas, Cross Sport	24	All	All	Windshield	Customer states windshield has visual imperfection