



# Technical Service Bulletin

---

## 97 Illuminated sill panel moldings on door sills do not work; U112100

97 24 08 2074150/1 June 3, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q4 e-tron, and Q4 Sportback e-tron	2024	All	Illuminated door sill

## Condition

### Customer statement:

The illuminated sill panel trim does not light up.

### Workshop findings:

The function can be activated via output diagnosis.

The following DTC is stored in the onboard supply control unit J519 (address word 0009)

- **DTC U112100:** Data bus missing message.

## Technical Background

The Target data container does not activate the illuminated sill panel moldings.

## Production Solution

New Target data container version available

## Service



# Technical Service Bulletin

Check the version of the target data container in the onboard supply control unit J519 (address word 0009) indicated by the red arrow in Figure 1.

**If the version is 0035 or above:** TSB does not apply, continue with normal diagnosis.

**If the version is below 0035,** proceed as follows:

1. Right click 0009 module.
2. Select Guided Functions.
3. Perform test plan “Replace control module”.
4. If prompted in the test plan, select the option the new module is already installed. The latest target data container will be automatically installed during the procedure.
5. Complete the test plan as prompted and confirm the function is now working after a 3-minute sleep cycle.

Address: 0009 System name: 0009 - Electronic Central Electrical (BCM).

<input type="checkbox"/> Identification:	
Data source:	Vehicle
Hardware part number:	1EA937089H
Part number:	1EA937089AA
Hardware version number:	H34
Software version number:	0311
Production date:	10.07.2023
Coding:	<input type="checkbox"/>
Coding:	000000
Ability to flash:	Unknown
System name:	SAM_H
ASAM base version:	BV_CentrElectUDS
ASAM 2D/ODX data set:	EV_SAMVW31x
ASAM 2D/ODX data set version:	004001
ASAM/ODX control module version being used:	EV_SAMVW31x_004
Target data container:	89A909514C
Version of the target data container:	0029
Equipment code:	00 00 00 00 00 00 00 00 01
System abbreviation:	J519

Figure 1: Version of target data container

**NOTICE**

**Do not replace any parts for this concern. Only the replacement test plan is to be performed, parts replaced for this concern under warranty will be charged back.**

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• 110 Up to 48 Months/50,000 Miles.</li> <li>• G10 for CPO Covered Vehicles – Verify Owner.</li> <li>• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
<b>Service Number:</b>	9710		
<b>Damage Code:</b>	0039		
<b>Labor Operations:</b>	Check target data container version	0150 0010	See SRT with associated operations



# Technical Service Bulletin

---

<b>Diagnostic Time:</b>	GFF	0150 0060	Time stated on the diagnostic protocol (Max 100 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB 2074150/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All part and service references provided in this TSB (**2074150**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.